and the second of the second of the second of	Last Annual Control and the Control of the Control	
	CLASSIFICATION SECRET/ SECURITY INFORMATION 25X1	Λ
OUNTRY	East Germany SECURITY INFORMATION 25X1.	
OPIC	Bremenhain Airfield	sorrec popul
3 4 6 4 4 4 6 7 7 7 7 4 4	see below PLACE ORTAINED 25X1A	5-30 9490 / - 4. a
VALUATION	PLACE OBTAINED ZONTA	1.19400-100700
ATE OF CON	・ 「中国の大学の大学の大学の大学の大学の大学の大学の大学の大学の大学の大学の大学の大学の	
ATE OBTAINE	D. TE PREPARED 9 October 1953	
EFERENCES.	25X1A	ac nec oper
	ENCLOSURES (NO. & TYPE)	
LaPPONING accessor		
THE RESERVE OF THE STREET		
and the second s	THE STORM CONTINUES AND THE SERVICE AND THE SE	nsama.
and the same of the state of the specific sections of the same of		
m. 11m m. m.		(**********************************
OURCE	25X1X	
X1X		
	Since the June 17 disturbances, construction work at Bremenhain airfield has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field.	
2.	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premembain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular	
	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October	
	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular taxiway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.	
2,	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September. The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started.	
3.	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular taxiway was to be built and had already been surveyed. However, construction work had not yet started by 11 September. The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started. In late August, construction work was completed on five small brick buildings,	
3.	has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the field. In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 Actober 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September. The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started. In late August, construction work was completed on five small brick buildings, allegedly officers billets, near the park of the Bremenhain estate. A spur track was to be built from the Lodenau-Rothenburg railroad line to the field dump. Three standard-gauge locomotives, one from Hoyerswerda and two from Luckau, were used for construction work.	

25X1

25X1

25X1

SHORET

		:				2 -				25X1A
	. 1									
	-	7.	Since about by aircraft Zone of Germ the zonal be aircraft use	coming from any. Almorrand a	om the Polis st every eve made flight	sh-occupie ening afte s of about	ed German te er nightfall : 15 minutes	rritory t	o the Sovie t crossed o	ver
	ž.		ork on the roork on the name of the name o	orthern t	hird of the	runway wa	is started o	n 8 Septe		
25X1X		9.	Work was und line. The tr removed and approximatel	ees and the local	elephone po residents September.	les along expected t A second	the Bremenh that the roa spur track	ain-Loden d would b was being	au road wer e blocked	
-			the railroad	I line tow	ard the woo	ds south c	r Lodenau.	1		
	3.0	0.	Major Mirone in Werder on a Bauunion of cover which thicker than because of t	31 Augus conducted consisted the top	t stated th work very b of two lay layer and a	at he was adly. He s ers of whi	now detache showed a pho ich the bott	ed to Roth stograph o com layer	enburg wher f a concret was conside	re Je erably
	3.	1.	On 1 Septemb of the runwa read and kil strip south except for a on a site no	y touched ometer ma of the Br middle s	both kilom rker 44.6 o emenhain-Lo trip. Four	eter marke f the Bren denau road large dred	er 47.6 of t menhain-Lode N was comple Ngers were u	the Rothen ensu road. eted by 1	burg-Bremer The runway September	<i>T</i>
25X1A		. [Cormo	d The c	da farancia de la constante de	n constant	rtónn senule e	t Decrease	nin ninfini	1.4
23/1/		1. I	confirm the	previous	tatements o picture.			ಚಿತ್ರಗ	Annex to	25X1A
25X1A			sheet 4655.		For locati	on of refe	erence point	s, see Ma	p GSGS 441.	39
25X1A		2. [ommer		ircraft obs ed in the S			g to the F	ourth Air	
25X1A	· ·	3	Commer Force constr construction	uction he	Mironenko adquarters Brand, Welz	in Werder.	. Previously	r, he also	Soviet Air inspected	•
					•					
					and the second second					